



I hereby certify that this correspondence is being deposited with the United States Postal Service on the date set forth below as First Class Mail in an envelope addressed to: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450
Date of Signature 11/17/05
And Deposit: 11/17/05

Daniel G. Radler
Daniel G. Radler, Reg. No. 43,028

COFC

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No.: US 6,945,829
Title: SELF-LOCKING SCREW CONNECTION
Issued: September 20, 2005
Serial No.: 10/797,372
Filed: March 10, 2004
Applicant: Carlo Finzer, et al.
Docket: 460868.90215DIVII

Request for Certificate of Correction

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Dear Sir:

Accompanying this Request for a Certificate of Correction is a completed form PTO/SB/44, entitled Certificate of Correction. In reviewing the above issued patent, printing errors were discovered in the specification which may affect the understandability of the specification.

Issuance of a Certificate of Correction for this patent is, therefore, requested. It is believed the listed errors are not due to Applicant, and that no fee is due. If this is not correct, and fee is required, please charge Deposit Account No. 17-0055 in the amount of the fee.

Respectfully submitted,

Date: 11/17/05

By: Daniel G. Radler

Daniel G. Radler
Reg. No. 43,028
Quarles & Brady, LLP
411 East Wisconsin Avenue
Milwaukee WI 53202-4497
(414) 277-5000

Certificate
NOV 30 2005
of Correction



PTO/SB/44 (02-01)

Approved for use through 01/31/2004. OMB 0651-0033

U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : US 6,945,829 B2

DATED : September 20, 2005

INVENTOR(S) : Finzer, et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 6, lines 23 -27 should be replaced with the following:

FIG. 51 is a longitudinal section along line 51-51 of FIG. 51a through the pin housing according to FIG. 49;

FIG. 51a is an end view of the pin housing according to FIG. 49;

FIG. 52 is a cross section along line 52-52 of FIG. 52a through the pin housing according to FIG. 49 in which the terminal receiving cavities are viewed from the mating side;

FIG. 52a is a side view of the pin housing according to FIG. 49;

MAILING ADDRESS OF SENDER:

Daniel G. Radler
Quarles & Brady, LLP
411 E. Wisconsin Avenue
Milwaukee, WI 53202

PATENT NO. US 6,945,829 B2

No. of additional copies



Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comment on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.

5816956 NOV 30 2005